


Evaluation Telescopic Handler		i	
Customer/Location	<b>Alliam / Bad Bentheim</b>	vers 02-22	
Date:	<b>16.10.2024</b>		
Machine / type:	<b>Manitou MRT2150+ Privilege</b>		
Serial No.:	<b>765341</b>	Hour reading:	
Inspector:	<b>Reinolf</b>	Year:	<b>2013</b>
CE <input checked="" type="checkbox"/> EPA <input checked="" type="checkbox"/>	air condition <input type="checkbox"/>	stability indicator <input type="checkbox"/>	auxiliary hydraulics <input checked="" type="checkbox"/>
coupler manual <input checked="" type="checkbox"/>	coupler hydraulic <input type="checkbox"/>	stabilizers <input checked="" type="checkbox"/>	3-way-steering mode <input checked="" type="checkbox"/>
<b>cab</b> seat, arm rests		cab door	<b>good with bit rust</b>
switches, warn lights	<b>2), good</b>	windows & mirrors	<b>(pict.136)</b>
gauges & lamps	<b>good, good</b>	wipers, washer	<b>good, good</b>
aircon / heater	<b>good, good</b>	floor mat	<b>wiper blades worn, 1)</b>
<b>engine</b> leaks &	<b>no aircon/heater</b>	cab structure	<b>good</b>
seals	<b>good</b>	cooling system	<b>good</b>
oil condition & level	<b>no leaks seen, good</b>	noises	<b>good</b>
exhaust & muffler	<b>good, good</b>	blow by	<b>good</b>
smoke, fume	<b>good, good</b>	belts & pulleys	<b>normal</b>
<b>exterior</b> chassis &	<b>good, good</b>	coolant condition	<b>minor</b>
outrigger engine	<b>normal good, good</b>	boom & tool carrier	<b>good, good</b>
hood	<b>good</b>	boom chain	<b>good, -39°C</b>
covers & fenders	<b>good, good good,</b>	boom slide bars	<b>good, good</b>
<b>power train</b> axles &	<b>good</b>	paintwork	<b>good</b>
pivot transmission	<b>good good, good</b>	rims, wheel nuts	<b>good, low air</b>
case axle drive	<b>3)</b>	universal joints	<b>good - as age</b>
shafts hydraulics	<b>good</b>	dif f erentials	<b>RHS rear rim dent</b>
hoses & lines	<b>good</b>	tie rods & sleeves	<b>good</b>
lift & tilt cylinders	<b>good</b>	steering cylinders	<b>good</b>
<b>functional test</b>	<b>good, good</b>	outrigger cylinders	<b>ample play</b>
steering modes drive	<b>good, good</b>	pumps & valves	<b>good</b>
operation brake/park	<b>120x150x1300x5cm</b>	load indicator	<b>good</b>
brake lift & tilt	<b>minor play</b>	boom extension	<b>good, good</b>
function <b>bucket &amp;</b>		stabilizers	<b>good</b>
<b>forks</b> forks		lights, batteries	<b>good</b>
quick coupler			<b>good</b>
<b>tires</b>			<b>good, good</b>
front right front left		bucket dimensions	<b>N/A</b>
rear right rear left		bucket condition	<b>N/A</b>
<b>problems, details</b>		man basket	<b>N/A</b>
	brand, type	mm (%) remaining	comments, size, damages
	<b>Michelin XF</b>	<b>15mm (75%)</b>	<b>445/70R22.5 side cut</b>
	<b>Michelin XF</b>	<b>10mm (50%)</b>	<b>cut</b>
	<b>Michelin XF</b>	<b>10mm (50%)</b>	
	<b>Michelin XF</b>	<b>11mm (50%)</b>	
<b>1)washer not working</b> <b>2)Seat adjustment stiff or not working (pict. 17)</b> <b>3)Lift cylinder slightly oily but not leak. Dust seal is out of place (pict. 127)</b>			
<b>The machine is in general good working condition.</b>			
transport dimensions L x W x H:		<b>7,0 x 2,4 x 3,1 m</b>	