

Evaluation Articulated Dump Truck				 	
Customer/location:	X	vers 11/16			
Inspector:	Chris				
Machine / type:	Volvo A30D	Hour reading:	10921		
Serial No. :	60XXX	Year:	2002		
CE <input checked="" type="checkbox"/> A/C <input checked="" type="checkbox"/>	EPA <input type="checkbox"/> auto lube <input type="checkbox"/>	retarder <input checked="" type="checkbox"/>	extended side walls <input checked="" type="checkbox"/>		
tailgate <input checked="" type="checkbox"/>	heated bed <input type="checkbox"/> secondary	steering <input type="checkbox"/>	Manual <input checked="" type="checkbox"/> Parts book <input checked="" type="checkbox"/>		
cab		cab door	good		
seat	cushion worn through	windows, mirrors	(1)		
switches	good	wipers	good		
gauges, warn lights	good	floor mat	good		
aircon / heat	good	cab structure	good		
engine		Serial No.			
leaks & seals	some oil residues	cooling system	good		
oil condition & level	good	blow by	minor		
exhaust, muffler	good	belts & filters	good		
smoke	normal	coolant condition	good		
exterior		cooler grills	good		
chassis & frames	good	bumpers & fenders	good		
engine hood	good	lights	good		
stairs, hand rails	good	paintwork	good		
power train		rims	good		
axles	good	universal joints	good		
transmission	transfer gear oily	brake disks	no visual access		
hydraulics		steering cylinders	(2)		
hoses & lines	good	pumps & valves	good		
lift cylinders	good	steering orbital	good		
functional test		steering	good		
stall speed 1st gear	1615	articulation play	moderate play		
transmission fwd.	not tested	body lift	good		
transmission rev.	not tested	electrics	batteries are weak		
retarder	not tested	diff locks	not tested		
brakes holding 1/min	1600	park brake	good		
truck body		pins	moderate play		
welding condition	good	tail gate	slight dents		
bed & liner condition	good	side wall condition	good		
tires	mm or % good	brand/make	cuts	remould	Ser. No.
front right	50%	(3)	<input type="checkbox"/>	<input type="checkbox"/>	
front left	50%		<input type="checkbox"/>	<input type="checkbox"/>	
center right	50%		<input type="checkbox"/>	<input type="checkbox"/>	
center left	50%		<input type="checkbox"/>	<input type="checkbox"/>	
rear right	50%		<input type="checkbox"/>	<input type="checkbox"/>	
rear left	50%		<input type="checkbox"/>	<input type="checkbox"/>	
tire size:	23.5R25				
problems, details					
(1) The window joint seals need to be replaced on the windsreen and the rear window.					
(2) home made pin on steering cylinder without a grease nipple.					
(3) The tire set has a tread type for wheel loaders.					
The machine is in good condition. Some smaller repairs and replacements recommended.					
dimensions for transport L x W x H in meter:		10,3 x 2,95 x 3,45			